

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In ~~the~~ Patent of:

SOICHIRO KAWAKAMI, et al.

Application No.: 09/676,090

Filed: October 2, 2000

For: RECHARGEABLE LITHIUM
BATTERY

U.S. Patent No.: 6,924,059 B1

Issued: August 2, 2005

Examiner: John S. Maples

Group Art Unit: 1745

January 18, 2006

Certificate
JAN 24 2006
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

01/20/2006 SZEWDIE1 00000050 6924059

01 FC:1811

100.00 **REQUEST FOR CERTIFICATE OF CORRECTION**
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

JAN 25 2006

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,



Damond E. Vadnais
Attorney for Patentees
Registration No.: 52,310

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 107613v1

JAN 25 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,924,059 ^{b1}

DATED : August 2, 2005

INVENTOR(S) : SOICHIRO KAWAKAMI, et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE

(*) "297 days." should read --237 days--.

COLUMN 1

Line 66, "using" should read --used--.

COLUMN 2

Line 6, "using" should read --used--.

COLUMN 4

Line 34, "mean" should read --means--.

COLUMN 6

Line 62, "lithium." should read --lithium battery--.

COLUMN 8

Line 28, "has an" should read --has a--;

Line 31, "an sealing" should read --a sealing--;

Line 34, "110a" should read --101a--;

Line 51, "110a" should read --101a--; and

Line 67, "relatively." should read --relatively thin--.

COLUMN 11

Line 7, "indicates an" should read --indicates a--; and

Line 30, "mental" should read --metal--.

COLUMN 12

Line 12, "comprises" should read --comprise--; and

Line 52, "(see." should read --(see,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,924,059

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

107611 (Form#30)



JAN 25 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,924,059 β^1

DATED : August 2, 2005

INVENTOR(S) : SOICHIRO KAWAKAMI, et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 3, "MOS₂," should read --MoS₂--.

COLUMN 14

Line 33, "isolating" should read --isolate--;

Line 47, "of," should read --of--; and

Line 55, "more" should read --more of--.

COLUMN 15

Line 7, "electrolytesolution)," should read --electrolyte solution)--.

COLUMN 16

Line 38, "battery is obtained." should read --battery--; and

Line 64, "an," should read --an--.

COLUMN 17

Line 8, "cellar" should read --cellular--;

Line 10, "cellar" should read --cellular--;

Line 40, "past" should read --paste--; and

Line 59, "past" should read --paste--.

COLUMN 18

Line 11, "50 μ ," should read --50 μ m--; and

Line 28, "insulating" should read --insulate--.

COLUMN 19

Line 6, "their" should be deleted; and

Line 35, "obtained" should read --obtain--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,924,059

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

107611 (Form#30)



JAN 25 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,924,059 ^{Bi}
DATED : August 2, 2005
INVENTOR(S) : SOICHIRO KAWAKAMI, et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20

Line 41, "dimetacrylate" should read --dimethacrylate--.

COLUMN 22

Line 10, "hours" should read --hours in--;

Line 24, "battery(s)" should read --battery(s) that--; and

Table 1, "battery in" should read --batteries in--.

COLUMN 23

Line 2, "hours" should read --hours in--;

Line 19, "in withstand" should read --in withstanding--; and

Line 24, "plat" should read --plate--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,924,059

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

107611 (Form#30)

➡

JAN 20 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,924,059 *B1*
DATED : August 2, 2005
INVENTOR(S) : SOICHIRO KAWAKAMI, et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE

(*) "297 days." should read --237 days--.

COLUMN 1

Line 66, "using" should read --used--.

COLUMN 2

Line 6, "using" should read --used--.

COLUMN 4

Line 34, "mean" should read --means--.

COLUMN 6

Line 62, "lithium." should read --lithium battery--.

COLUMN 8

Line 28, "has an" should read --has a--;
Line 31, "an sealing" should read --a sealing--;
Line 34, "110a" should read --101a--;
Line 51, "110a" should read --101a--; and
Line 67, "relatively." should read --relatively thin--.

COLUMN 11

Line 7, "indicates an" should read --indicates a--; and
Line 30, "mental" should read --metal--.

COLUMN 12

Line 12, "comprises" should read --comprise--; and
Line 52, "(see." should read --(see,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,924,059

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,924,059 β |

DATED : August 2, 2005

INVENTOR(S) : SOICHIRO KAWAKAMI, et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 3, "MOS₂," should read --MoS₂--.

COLUMN 14

Line 33, "isolating" should read --isolate--;

Line 47, "of," should read --of--; and

Line 55, "more" should read --more of--.

COLUMN 15

Line 7, "electrolytesolution)," should read --electrolyte solution)--.

COLUMN 16

Line 38, "battery is obtained." should read --battery--; and

Line 64, "an," should read --an--.

COLUMN 17

Line 8, "cellar" should read --cellular--;

Line 10, "cellar" should read --cellular--;

Line 40, "past" should read --paste--; and

Line 59, "past" should read --paste--.

COLUMN 18

Line 11, "50 μ ," should read --50 μ m--; and

Line 28, "insulating" should read --insulate--.

COLUMN 19

Line 6, "their" should be deleted; and

Line 35, "obtained" should read --obtain--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,924,059

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

107611 (Form#30)



JAN 25 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,924,059 β 1

DATED : August 2, 2005

INVENTOR(S) : SOICHIRO KAWAKAMI, et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20

Line 41, "dimetacrylate" should read --dimethacrylate--.

COLUMN 22

Line 10, "hours" should read --hours in--;

Line 24, "battery(s)" should read --battery(s) that--; and

Table 1, "battery in" should read --batteries in--.

COLUMN 23

Line 2, "hours" should read --hours in--;

Line 19, "in withstand" should read --in withstanding--; and

Line 24, "plat" should read --plate--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,924,059

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

107611 (Form#30)



JAN 25 2006